



## Part Numbering System and Ordering Information



**WE 4/0A - 4A**

WE Connection      4/0 AWG      #4 AWG



**WT 2A - 2AS**

WT Connection      #2 AWG      #2 AWG, Solid

**Additional Options:**

Wear Plate - Add Suffix "G" to end of part number.

Heavy Duty Connections - Add Prefix "HD" to beginning of mold part number.

Split Crucible Molds - Add Suffix "-S" to end of mold part number.